Product Recovery Tank Discharge Lateral MW3 Secondary Treatment Primary Treatment (clear well) Product Skimmer Monitoring Port Product 2376.8 Soil Backfill Filter Groundwater 2375.8 Grit/Sludge Removal Baffle 3/31/04 Perforated Discharge Pipe (1% slope min) Gravel Drainage Gallery Submersible Pump Product Recovery and Treatment System **NTS**

Priceless Gas Cleanup Action Work Plan Date: 4/14/2004 Figure 4

File: priceless\plgproductrecovery2004.FCW

- 8